

button. (Each time the button is pressed, inch and metric digits will be displayed alternatively).

(3) Apply normal measuring pressure on slider to close the external measuring jaws. Then press "zero" button to reset the display to zero.

#### A Measurements of external dimensions.




#### C.Measurements of steps.




E. Differential method measurement (Application of zero setting)

### B.Measurements of internal dimensions.



D.Measurements of depth.



OFF ON

# ● MAINTENANCE INSTRUCTIONS

1. Keep the caliper clean and dry(Liquid can damage the slider)

2. Faces should be cleaned gently with cotton fabrics. Never use petrol, acetone and other organic solutions.

3.In order to save power, turn off the unit when caliper is going to stay idle for some time.

4 Never apply any electric pressure on any part of the caliper and never use an electronic pen for the fear of damaging its chip.

5. For other notes please refer to the conventional calipers.

## BATTERY REPLACEMENT

Flashing of digits shows a flat battery. Take off the battery cover in the direction shown by the arrow and replace the battery (positive side facing out).

### TROUBLE SHOOTING

