

- For use with TIG and MIG electronic welders
- Keeps wire from going through hole
- Copper pad dissipates heat
- Saves time and labor, quicker cleaner welds

Position magnetic base so that the copper pad is behind joint or hole to be welded. Adjust knob up or down so that copper pad is flush against the back of void to be welded, and weld up hole. Remove tool and grind the excess weld.

Made in Taiwan Exclusivly for VIM Tools, PATENT PENDING

DURSTON MANUFACTURING COMPANY

1395 E. PALOMARES AVE., LAVERNE , CA 91750 USA 800-728-4942 * FAX 909-593-0302

WWW.VIMTOOLS.COM * E-MAIL DONO@VIMTOOLS.COM

