

POOL BLASTER® FUSION™ PV-5

QUICK START GUIDE GUIDE DE DÉMARRAGE RAPIDE GUÍA DE INICIO RÁPIDO




A

A.1



A.2



A.3




Adapter - Not included
Adaptateur - non inclus
Adaptador - No incluido



Charging time: 4 hours
Temps de charge: 4 heures
Tiempo de carga: 4 horas




B



C



D



OPTIONAL - NOT INCLUDED
FACULTATIF - NON INCLUS
OPCIONAL - NO INCLUIDO

E



Push for ON / OFF.

Pousser pour MARCHÉ / ARRÊT.

Empuje para ENCENDIDO / APAGADO.

Submerge immediately after pushing ON.


Submerger immédiatement après avoir appuyé sur MARCHÉ.

Sumerja inmediatamente después de presionar ENCENDIDO.



F

Maintenance • Entretien • Mantenimiento



WaterTechCorp.com

For more maintenance information, refer to the Operator's Manual.

Pour plus d'informations de maintenance, reportez-vous au Manuel de l'opérateur.

Para más información de mantenimiento, refiérase al Manual de Operador.