

MODEL 5805 MPACT FITTING CLEANER

Grease that has hardened in a fitting or joint often forces equipment out of service for disassembly and repair. Lincoln's new Impact Fitting Cleaner flushes lubricant passages of dried or separated grease. The Model 5805 clears blockages so that fresh grease can be applied.

- Clears hardened grease from fittings and joints
- Eliminates the need to disassemble joints or replace fittings
- Forces light oil through clogged lubrication points
- Includes:
 - Steel drive cylinder
 - Hardened piston
 - Safety shield
 - High-pressure hose for hard-to-access fittings
 - Spare drive seals
 - Lincoln's Model 5852 coupler

A TIME-SAVING ALTERNATIVE TO FITTING REPLACEMENT AND JOINT DISASSEMBLY