
WIRING INSTRUCTIONS



	WIRING SPECIFICATIONS						
Wire		Origin or					
No.	Color	Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation			
1	White	Cordset	3-1/4"	Strip 5/16" and tin. Connect to '1↑' on switch.			
2	Black	Cordset	3-3/4"	Strip 5/16" and tin. Connect to '2↑' on switch.			
ЗА	White	23-94-0520		From the top left field position, connect tinned end to '1' on switch.			
3B	White	23-94-0520		From top left field position, connect terminal to top right field position.			
4A	Black	23-94-0510		From bottom right field position, connect terminal to bottom left field position.			
4B	Black	23-94-0510		From the bottom right field position, connect terminal to top brush.			
5	Black or Blue	Remote Mod.		Component of 14-20-3155. Connect to bottom brush.			
6	Black or Yellow	Remote Mod.		Component of 14-20-3155. Connect to '5' on right side of switch.			
7	Black	Remote Mod.		Component of 14-20-3155. Connect tinned end to '2a' on switch.			

All leads must be held to $\pm 1/8$ ". All lead lengths are before stripping.

TERMINAL DESCRIPTION						
Code	Part No.	Qnty.				
T1	23-94-1060	4				
T2	23-94-0017	2				
Т3	23-94-0010	1				